


Walnut Clay (marly shale)  
 Goodland Limestone



Water Seepage Zone

Lower electrical resistivity zone isolates seepage zones identified at the dam fill contact with native soil. IP anomaly provides additional confirmation of fluid flow at this location.

